

LINK TO SIGN OFF FORM (JS BUTTON)

Workorders Open

Workorder-Task	Planned End Date	House Details	Work Description	Reason Comments	entryID	
17959714-001	4/20/2023	CLI 201 TV	INSPECT REPAIR FASCIA BOARD UNDER GUTTER INSPECT REPAIR FASCIA BOARD UNDER GUTTER AT FRONT OF HOUSE		202791	Close Workorder X
17925676-002	09/05/2023	CLI 247	RPL DOORS, ROLLERS & LOCK SECURE TILE replace bathroom door, adusdt rollers of replace the linnen cupboard doors and		204103	Close Workorder X
19108134-001	17/06/2023	CLI 323	API RPR,RPL STEP TREADS & FACIA ROTTEN STEPS HANDRAILS & FLOOR BOARDS ON VERANDAS NEED		209268	Close Workorder X